

Copy Attached to report submitted  
for information

CHLORINE RESIDUAL TEST		FOR THE MONTH OF:	DECEMBER 2015
DATE	SAMPLING AREA	ZONE NUMBER	RESIDUAL (PPM)
1	MA-AO PUMPHOUSE	3	1.5
2	PRK BACUS - MAAO	1	0.4
3	SUHA PUMPHOUSE	19	3
4	ROADSIDE - NAPOLES	19	0.5
5	PRK. PAHO - NAPOLES	19	0.6
6	CANUSLAY - NAPOLES	19	0.3
7	PULANG DUTA - LAG-ASAN	10	0.3
8	STA. CATALINA - LAG-ASAN	10	0.3
9	SAN GABRIEL - BALINGASAG	7	0.4
10	SAN ESTEBAN - LAG-ASAN	10	0.3
11	HOSPITAL -BALINGASAG	7	0.3
12	SOUTHBAY -SAMPINIT	20	0.4
13	PRK ANAHAW - SAMPINIT	20	0.3
14	PRK. BACUS - MA-AO	1	0.3
15	PRK. PUCATOD - MA-AO	1	0.3
16	KM 15 - CALUMANGAN	4	0.3
17	DBI - CALUMANGAN	4	0.3
18	PINANUY-AN - SAMPINIT	10	0.3
19	CAN-ITUM - SMPINIT	20	0.3
20	STA CATALINA - LAG-ASAN	10	0.4
21	DBI - CALUMANGAN	4	0.3
22	KM 15 - CALUMANGAN	4	0.3
23	PRK BACUS - MAAO	1	0.3
24	PRK PAHO - NAPOLES	19	0.7
25	LUMANGOB - NAPOLES	19	0.5
26	RELOCATION SITE	10	0.4
27	PUNTA PLAYA	13	0.3
28	PINANUY-AN - SAMPINIT	20	0.3
29	PUNTA PLAYA - POBLACION	20	0.3
30	HOSPITAL -BALINGASAG	7	0.3
31	SAN GABRIEL - BALINGASAG	7	0.4

SUBMITTED BY:

  
PEDRITO N. BPACTA  
Water Utilities Management Officer B

SAMPLES COLLECTED AND TESTED BY:

  
BENJE CARABALLO